



# PATROL EMERGENCY PREPAREDNESS WORKSHOP – PARTICIPANT PACKAGE

## ALP EXERCISE



# PATROL EMERGENCY PREPAREDNESS WORKSHOP – PARTICIPANT PACKAGE

## ALP EXERCISE



# PATROL EMERGENCY PREPAREDNESS WORKSHOP – PARTICIPANT PACKAGE

## ALP EXERCISE

### Overhead Facilities Storm Restoration Report

<input type="checkbox"/> Need to Patrol	TCMS Ticket # 1412	SRR # CE01-06132-003-L-01
<input type="checkbox"/> Clear – Patrolled	TCMS Ticket Type LATERAL	Patrolled by JAY WILKINS
<input type="checkbox"/> Damage – Patrolled	TCMS Ticket Date 10/31/05	Patrol Date 10/31/05
<input type="checkbox"/> Repaired / Restored	TCMS Feeder # 6132	
<input type="checkbox"/> Cancelled by TCMS	TCMS Current List	
	TCMS Ticket Key	Essential Customer
		<input type="checkbox"/> Y <input checked="" type="checkbox"/> N
		Accessible
		<input checked="" type="checkbox"/> Y <input type="checkbox"/> N

Substation Name DOUGLAS	Map # AJ-0246	From Switch 613204
Substation # 061	Storm Center CEO	Two Switch 1 613205
Address 1 P N/O MENDOZA AV	Customer Count 32	Two Switch 2
Voltage 13KV	Feeder # 6132	Two Switch 3
Co-ordinate 8-6853-7665-0-4	Storm Area CENTRAL	Two Switch 4
FPL id	Miles of Conductor	Feet of Conductor

Rapid Patrol Assessment Information	Feeder patrol – Number of Laterals Damaged:	
	All Patrols	Lateral Patrols Only: # of TX to Replace
# Poles Broken 0	25 KVA TX	75 KVA TX
# Spans of Primary Conductor Down 1	37 KVA TX	100 KVA TX
# Trees to Trim 1	50 KVA TX	167 KVA TX
	Environmental Concerns Observed:	<input type="checkbox"/> Y <input type="checkbox"/> N